GOVERNMENT OF ANDHRA PRADESH ABSTRACT

General Administration Department – Secretariat Buildings – Repairs to Asst. Secretary to Chief Minister office, 7th Floor, L-Block in the premises of A.P. Secretariat – Submission of estimate – Administrative Sanction – Orders – Issued.

GENERAL ADMINISTRATION (SB) DEPARTMENT

G.O.RT.No. 810 Dated: 13.03.2015

Read:-

From the Executive Engineer (R&B) Buildings Division, Hyderabad. Lr.No.EE(R&B)/Bldgs Division / 2014-15, Dt: 27.1.2015 &&&

ORDER:

In the circumstances reported by the Executive Engineer (R&B) Buildings Division Hyderabad in the reference read above and after examination of the matter, Government hereby accord administrative sanction for an amount of Rs.11,50,000/- (Rs.8,70,000-00 + Rs.2,80,000-00) (Eleven Lakhs Fifty Thousand only) towards urgent Repairs to Asst. Secretary to Chief Minister office, 7th Floor, L-Block in the premises of A.P Secretariat, Hyderabad and urgent repairs to water supply and sanitation arrangements to the Asst. Secretary to Chief Minister Office on the responsibility of Executive Engineer (R&B) Buildings, Hyderabad and also subject to due procedure and also production of the work done certificate at the time of issue of L.O.C.

- 2. The expenditure shall be debited to the head of account "2059 Public works 01 Office buildings MH 053 Maintenance and repairs SH(10) Buildings of General Administration Department 270 Minor works 272 Maintenance" from out of budget provision for the F.Y.2015-16.
- 3. This order does not require the concurrence of Finance Department in terms of Circular Memo.No.7088/049/A/BG/2000-1, dated 25.10.2002.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

MUKESH KUMAR MEENA SECRETARY TO GOVERNMENT (POLL.)

To

The Executive Engineer (R&B) Buildings Division, Hyderabad.

Copy to:

The Dy.E.E.(R&B) Buidlings, Sectt. Sub-Division.

//Forwarded By Order//

SECTION OFFICER.